

WPR26LA182

INVESTIGATION PHOTOGRAPHS/IMAGES



Photograph 1 - Wreckage prior to removal from accident location (Courtesy of KRIR Airport Ops)



Photograph 2 - Damage, right wingtip (Courtesy of FAA)




Photograph 3 - Damage, right wing (Courtesy of FAA)



Photograph 4 - Bent fence/post at point of impact (Courtesy of FAA)



Photograph 5 - Bent fence/post at point of impact (Courtesy of FAA)



Photograph 6 - N5832L Flight Path Diagram, Public ADS-B Data, Final Approach Leg