

WPR26LA200

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of right wing damage (Courtesy of Airport Operations)



Photograph 3 - View of right aileron damage (Courtesy of Airport Operations)