

WPR26LA206

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Wreckage and Location (Courtesy of Big Creek Lodge)



Photograph 2 - Airplane Wreckage, Right Side (Courtesy of Big Creek Lodge)



Photograph 3 - Damaged Ground Vehicle (Courtesy of Big Creek Lodge)