


WPR26LA210

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Prior to Recovery (Courtesy of pilot)



Photograph 2 - Damage (Courtesy of SLE Ops)



Photograph 3 - Damage (Courtesy of SLE Ops)



Photograph 4 - Damage (Courtesy of SLE Ops)



Photograph 5 - Damage (Courtesy of SLE Ops)