

WPR26LA220

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Pilot)



Photograph 2 - View of right wing damage (Courtesy of Pilot)



Photograph 3 - View of right wing damage (Courtesy of Pilot)