

WPR26LA222

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of inverted accident airplane (Courtesy of National Park Service)



Photograph 2 - View of forward fuselage damage (Courtesy of National Park Service)



Photograph 3 - View of aft fuselage damage (Courtesy of National Park Service)