

WPR26LA241

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of left elevator damage (Courtesy of Airport Operations)



Photograph 3 - View of left aileron damage (Courtesy of Airport Operations)