

WPR26LA265

INVESTIGATION PHOTOGRAPHS



Figure 1: View of airplane's final resting position next to runway. (Courtesy of Law Enforcement)



Figure 2: View of airplane's propeller contact marks leading down the runway. (Courtesy of Law Enforcement)